



417400

EN

Digital Pocket Multimeter

Translation of the original user's manual

Contact information for our customer and consulting centre:

www.extol.eu service@madalbal.cz

Manufacturer: Madal Bal a. s., Průmyslová zóna Příluky 244, 76001 Zlín, Czech Republic
Date of issue: 21. 10. 2019

SAFETY INFORMATION

This measuring device is designed according to the requirements of norm EN 61010 for electronic measuring devices with a measurement category of CAT III 300 V and pollution level 2.

WARNING

Carefully read this user's manual before first using the device and keep it with the product so that a user can become acquainted with it. Prevent this user's manual from being destroyed.

WARNING

In order to prevent causing injury by electrical shock or other types of injuries, adhere to the following instructions.

Introduction

This device is a compact digital measuring device with a display that shows the maximum value of 1 999, whilst the first digit may have a value of 0 or 1 and the following three digits may have a value from 0 to 9. The device is intended for measuring direct- and alternating-current voltage, direct current, resistance, diodes and continuity. It has a polarity indicator, low battery power indicator and is small in size and has a low weight. This useful testing device is very portable.

SAFETY WARNINGS

- Do not use this measuring device when it is damaged. Prior to using the device, check its case. Pay attention particularly to the insulation around the connectors.
- Check that the testing wires/probes do not have damaged insulation, or whether there is any visibly exposed metal on them. Check whether the testing wires/probes are interrupted at any point. Prior to using the measuring device, replace any damaged test wires/probes.
- Do not use this measuring device when it is not functioning correctly. The level of protection may be reduced. In the event of any doubts, have the measuring device inspected and repaired.
- Do not use this measuring device in the vicinity of flammable or explosive gases, fumes or powder substances.
- Do not use between terminals or between terminals and ground with a voltage greater than the nominal voltage that is indicated on the measuring device
- Before using it, check the working order of the measuring device by measuring a known voltage.
- When measuring current, turn off the power supply to this circuit before connecting the device to it. During measurement, the device must be connected to this circuit in series.
- When performing repairs on the measuring device, always use only original parts.
- Be careful when working with voltages exceeding the effective value of 30 VAC, 42 Vpeak or 60 V DC. Such voltage values present a risk of injury by electrical shock.
- Do not touch the uninsulated metal parts of the measuring probes while performing measurements. Hold the probes by the insulated grip parts.
- Do not use this device when it is wet or damp, if the test wires are wet or damp or if your hands are wet or damp.
- When connecting the test wires during testing, first connect the black test wire and then the red test wire. When disconnecting the test wires, disconnect the red wire first.
- Before opening the rear cover, remove the test wires/probes from the tested circuit.
- Do not use this measuring device if the rear cover is removed or loose.
- If you wish to prevent reading off incorrect values, which could result in injury by electrical shock or to other injuries to persons, replace the batteries in the measuring device as soon as the low battery power level indicator (⚡) appears on the display.
- To prevent injury by electrical shock, prevent coming into contact with exposed wires with hands or skin and ensure that you are not grounded when working with this measuring device.

WARNING

- For safety reasons, do not use the tester to measure electrical installations requiring a level IV overvoltage category (CAT IV). The specifications for the individual overvoltage categories CAT I to CAT IV according to EN 61010-1 are provided below and are illustrated in the picture.


WARNING

- The device must be used for measuring using measuring probes intended only for the given CAT overvoltage category with the specified maximum voltage for the given voltage category, i.e. measuring probes with a specified CAT III for the specified voltage cannot be used for measurements on CAT IV installations.

WARNING

- For safety reasons, do not use the CAT III overvoltage category measuring device to measure electrical installations requiring a level IV overvoltage category (CAT IV). The specifications for the individual overvoltage categories CAT I to CAT IV according to EN 61010-1 are provided below and are illustrated in the following picture.
- Electrical installations requiring an overvoltage category IV (CAT IV) measuring device are the following: Electrical equipment located in the near vicinity of a building's power source, between the input into the building (junction box) and the main switchboard. Such equipment may include, for example, tariff electricity meters and primary overvoltage protection devices.
- Electrical installations requiring an overvoltage category III (CAT III) measuring device are the following: Equipment that is part of the electrical installation in a building. Such equipment includes power sockets, circuit breaker boards and certain other mains power control installations. The measuring device meets the requirements for the CAT III protection level only up to the specified voltage value; and it must not be used for measuring installations requiring the CAT III level which are at higher voltages.
- Overvoltage category II (CAT II) includes equipment intended to be powered from the building installations. This applies both for equipment connected to power sockets as well as for permanently connected equipment.

- Overvoltage category I (CAT I) covers equipment intended for connection to mains power, where the equipment incorporates measures that significantly and reliably reduce transitional overvoltage to a level that cannot present a hazard. Overvoltage category I (CAT I) is not relevant to norm EN 61010-1, according to which the measuring device has been tested.
- A measuring device with a higher overvoltage category (CAT) can be used to measure installations belonging to a lower overvoltage category, e.g. a multimeter with CAT III protection for the defined voltage can be used to measure CAT II installations in the permitted voltage range, however, a CAT III multimeter cannot be used for measuring installations belonging in category CAT IV.



WARNING

- The device must be used for measuring using measuring probes intended only for the given CAT overvoltage category with the specified maximum voltage for the given voltage category, i.e. measuring probes with a specified CAT III for the specified voltage cannot be used for measurements on CAT IV installations.

SAFETY WARNINGS


To prevent possibly damaging this measuring device or tested appliance, proceed according to the following instructions:

- Prior to testing resistance, diodes or continuity, disconnect the power supply from the circuit and discharge all capacitors.
- Use the correct function and range for your measurement.
- Before measuring current, check the fuse of the device and turn off the power supply to the circuit even before connecting the device to the circuit.
- Prior to using the function switch or before turning the rotary switch, disconnect the test wires/probes from the tested circuit.

MEANING OF MARKINGS

	Alternating-current voltage
	Direct current/voltage
	Direct- and alternating-current voltage
	Attention, risk of danger, study the user's manual.
	Attention, there is a risk of injury by electrical shock.
	Grounding terminal
	Fuse
	Meets respective EU requirements
	This measuring device is completely protected using double or heavy-duty insulation.
	Read the user's manual before using the device.
	For indoor use; protect it against rain and the entry of water
IP 20	Protection (protect against rain and the entry of water)
Overvoltage category	Overvoltage category; 300 V CAT III
Degree pollution 2	Only non-conductive pollution occurs; in certain cases conductivity caused by temporary condensation is expected (EN 61010-1).
Working t/p, / < 2000m	Operating temperature/relative humidity/metres above sea level.
	The unusable device must not be disposed of with communal waste, but must be handed over at a waste collection facility for electrical equipment. Prior to disposal, remove the batteries and hand the batteries over at a battery collection point.

Front panel



- Display** – The LCD display shows the maximum value of 1 999, whilst the first digit may have a value of 0 or 1 and the following three digits may have a value from 0 to 9.
- Function switch** – It is used for selecting the desired function.
- Range dial** – It is used for selecting the required range and also for turning the device on and off. When this device is not being used, set the range dial to the "OFF" position to turn off the device.
- Test probes (test wires)**

Basic technical data

Display: The LCD shows the maximum value of 1 999, whilst the first digit may have a value of 0 or 1 and the following three digits may have a value from 0 to 9.**Negative polarity indicator:** The negative polarity symbol "−" is shown on the display automatically**Scanning frequency:** About two to three times per second**Batteries:** 12 V 23 A 1 piece, type VA23A or equivalent**Insufficient battery voltage indicator:** "⚡" is shown on the display**IP protection level:** IP20**Operating environment:** Temperature: 0°C to 40°C, altitude above sea level < 2000 m a.s.l.**Relative humidity:** < 75 %**Storage temperature (without the battery):** Temperature: -10°C to 40°C

Relative humidity: < 85 %

Dimensions: 124 × 71 × 21 mm**Weight:** 112 g including the battery

ATTENTION

The battery is already inserted inside the device by the manufacturer, but for safety reasons it is not conductively connected with the device. For this reason, to access the battery, remove the screws at the rear of the device and take off the device's rear cover. Then remove the insulation material from the battery and insert it back into the battery compartment as per the indicated polarity and then secure the device's rear cover back in place using the screws.

Accuracy specifications

The measurement accuracy provided in the following tables applies for the temperature range of 18°C–28°C at a humidity of 75% and at an altitude up to 2000 metres above sea level.

Note:

The "≤" symbol preceding the numerical value in the "RANGE" column in the following tables denotes that the device can also measure values that are lower than those indicated in the respective table row.

DIRECT-CURRENT VOLTAGE

Scope	Resolution	Accuracy	Overlap indicator
≤ 2 V	0.001 V	± (0.5 % + 5)	"OL" is shown on the display
≤ 20 V	0.01 V		
≤ 200 V	0.1 V		
≤ 300 V	1 V		_____ [1]

Input impedance: 10 MΩ**Maximum permitted input voltage:** 300 V, direct-current voltage [1] If the measurement result is > 310 V, then the display will show "OL" instead of the measured value.

ALTERNATING-CURRENT VOLTAGE

Scope	Resolution	Accuracy	Overlap indicator
≤ 200 V	0.1 V	± (1.0 % + 5)	"OL" is shown on the display
≤ 300 V	1 V		_____ [1]

Input impedance: 10 MΩ**Frequency range:** 40 Hz to 400 Hz**Maximum permitted input voltage:** 300 V, alternating rms**Response:** Average, calibrated in the effective sine wave value [1] If the measurement result is > 310 V, then the display will show "OL" instead of the measured value.

DIRECT CURRENT

Scope	Resolution	Accuracy	Overlap indicator
≤ 200 mA	0.1 mA	± (0.5 % + 5)	"OL" is shown on the display

Overload protection: Quick fuse 250 mA / 300 V

RESISTANCE

Scope	Resolution	Accuracy	Overlap indicator
≤ 2 kΩ	0.001 kΩ	± (1.0 % + 2)	"OL" is shown on the display
≤ 20 kΩ	0.01 kΩ		
≤ 200 kΩ	0.1 kΩ		
≤ 2 MΩ	0.001 MΩ		

Maximum open circuit voltage: 1 V**Overload protection:** 300 V, alternating rms

Procedure for calculating measurement accuracy

The alternating voltage value is shown on the display, e.g. 180.1 V.

According to the table, for the range ≤ 200 V the specified accuracy is: ± (1.0% + 5).

Measurement accuracy is calculated as follows:

- Calculate the uncertainty range: ±1% from 180.1 V; the uncertainty range is: 178.3-181.9 V
- To the decimal value then add the number "5", the measured voltage is in the range: 178.8-182.4 V

The temperature correction coefficient for calculating accuracy at <18°C or >28°C is: 0.2

At a measurement temperature of <18°C or >28°C, the calculation procedure is the same as above, however, 0.2 is added to X%, accuracy is then calculated according to ± (1.2% + 5).

DIODE AND CONTINUITY TEST

Scope	Description	Note
	The display shows the approximate reduction of diode bias.	Voltage on an open circuit: approx. 2.2 V Test current: approx. 0.7 mA
	If the buzzer is sounded, the measured circuit is not interrupted.	—

Operating instructions

MEASURING DIRECT-CURRENT VOLTAGE

- Set the function switch to the position "V".
WARNING: If the function switch is not set precisely to position "V", the device will most probably not perform the measurement or will not function normally.
- Set the range switch to the position corresponding to the required voltage range. If you do not know the magnitude of the measured voltage in advance, first select a higher range and then gradually lower this range until you reach a satisfactory range.
- Connect the test probes to the source or to the measured circuit. Connect the red probe to the positive terminal and the black probe to the negative terminal.
- Read off the value shown on the display. The polarity of the red test probe will be indicated as correct.

WARNING

- For reasons of protection against injury by electrical shock or avoiding damage to this device, do not measure voltages greater than 300V.
- If the 300 V range is used, the display will show the symbol "⚡", which informs you that you must be very careful when measuring high voltage.

MEASURING ALTERNATING-CURRENT VOLTAGE

- Set the function switch to the position "V".
WARNING: If the function switch is not set precisely to position "V", the device will most probably not perform the measurement or will not function normally.

- Set the range switch to the position for the voltage range "200 V" or "300 V". If you do not know the magnitude of the measured voltage in advance, first select a higher range and then gradually lower this range until you reach a satisfactory range.
- Connect the test probes to the source or to the measured circuit. Connect the red probe to the positive terminal and the black probe to the negative terminal.
- Read off the value shown on the display.

WARNING

- For reasons of protection against injury by electrical shock or avoiding damage to this device, do not measure voltages greater than 300V.
- If the 300 V range is used, the display will show the symbol "⚡", which informs you that you must be very careful when measuring high voltage.

MEASURING DIRECT CURRENT

- Set the function switch to the position "A".
WARNING: If the function switch is not set precisely to position "A", the device will most probably not perform the measurement or will not function normally.
- Set the range switch to the position corresponding to the range "200 mA".
- Turn off the power supply to the measured circuit. Then discharge all capacitors.
- Disconnect power supply to the circuit that you wish to measure and connect the test probes in series in this circuit.
- Turn on the power supply to the circuit and then read off the value on the display. The polarity of the red test probe will be indicated as correct.

MEASURING RESISTANCE

- Set the function switch to the position "Ω".
- Set the range switch to the position corresponding to the measured resistance range.
- Connect the test probes to the measured resistance.
- Read off the value shown on the display.

Note:

- When measuring a resistance the value of which is greater than 1 MΩ, the stabilisation of the value on the display may take several seconds. When measuring high resistances, this is normal.
- If the test probes are in an open circuit state, the display will show "OL", which will indicate that the range has been exceeded.

WARNING

Before measuring, disconnect the power supply to the measured circuit and completely discharge all capacitors.

MEASURING CONTINUITY

- Set the function switch to position "Ω" and the range switch to position "⦿".
- Connect the test probes to the measured circuit.
- If the buzzer is sounded, the measured circuit is not interrupted.

WARNING

Before performing the test, disconnect the power supply to the measured circuit and completely discharge all capacitors.

TESTING DIODES

- Set the function switch to position "Ω" and the range switch to position "▶".
- Connect the red test probe to the anode of the tested diode and the black test probe to the cathode of this diode.
- The display shows the approximate reduction of the diode bias in mV. If the connection is performed in reverse, the display will show the "OL" symbol.

Maintenance

Apart from the replacement of the battery and the fuse, never attempt to perform any repairs or servicing on this device.

Regularly wipe the surface of the device's cover using a damp cloth and diluted cleaning agent. Prevent water from entering the device. Do not use abrasive cleaning products or solvents.

REPLACING THE BATTERY AND FUSE

In the event that the "⚡" symbol appears on the display, this means that the battery is flat and must be replaced with a new one. Remove the screws on the rear cover and take off this cover. Replace the battery with the same type as is in the device (12 V 23A, type VA23A or equivalent). When inserting the battery, heed the designated polarity +/-. Put the rear cover back on and screw in the screws.

In the event that you wish to replace the fuse, use the aforementioned method to remove the rear cover. Then take out the burnt fuse and replace it with a new fuse with the same current rating value. Put the rear cover back on and screw in the screws. This measuring device uses a single fuse: F 250 mA / 300 V, quick-break, ⚡V 5 × 20 mm

WARNING

- If you wish to prevent reading off incorrect values, which could result in injury by electrical shock or to other injuries to persons, replace the batteries in the measuring device as soon as the low battery power level indicator (⚡) appears on the display.
- Before opening the rear cover or the body of the device, first turn the device off and disconnect all test probes from the tested circuit.
- To prevent causing damage or injury, install only the specified replacement fuse into this device.

Warranty period (rights relating to faulty performance)

- The product is covered by a 2-year warranty from the date of sale according to law. If requested by the buyer, the seller is obliged to provide the buyer with the warranty conditions (rights relating to faulty performance) in written form according to law.

Storage

Store the device in a dry place out of the reach of children, at temperatures up to 40°C and protect it against frost, ingress of water and high humidity.