



INDIAN SCOUT BOBBER 1130 '18

REF 9765N

SOPORTE INTERMITENTE TRASERO / REAR TURN SIGNAL SUPPORT / HINTERE BLINKENDE HALTER



ID.	PIEZA / PART	DESCRIPCIÓN	DESCRIPTION	QTY.	REF.:
1		Soporte intermitentes	Turn light support	2	SOPINT20-0-020A SOPINT20-0-020B
2		Tornillo M6x15 DIN1001 (NEGRO)	M6x15 DIN1001 screw (BLACK)	2	TORNI-I7380-403
3		Tuerca M6 DIN6923	M6 DIN6923 nut	2	TUERCAEM6G-0213
4		Tapón tornillo DIN1001	Screw cap DIN1001	2	TAPON-----86
5		Intermitentes (No incluidos)	Turn signals (Not included)	2	9556N

**CONSULTAR EN NUESTRA PAGINA WEB LA DISPONIBILIDAD DEL VIDEO DE MONTAJE DE ESTA REFERENCIA.
CONSULT OUR WEBSITE THE VIDEO MOUNT AVAILABILITY OF THIS REFERENCE.**




INDIAN SCOUT BOBBER 1130 '18

INSTRUCCIONES DE MONTAJE - MOUNTING INSTRUCTIONS - MONTAGEANLEITUNG

1

**DISASSEMBLY
DESMONTAJE**



2

**ASSEMBLY
MONTAJE**

